

Basic Aviation Risk Standard

Contracted Aircraft Operations

ISASI – Wellington NZ

Jun 2017



Elimination of unnecessary multiple audits

Standardization of audits


Centralized quality assurance of the audit process


A mechanism to allow mutual acceptance of audit reports by companies in the sector

Cost efficiency

A centralized incident/accident database for the sector

A process to ensure that the industry standard reflects the evolution of the sector









Figure 1: Schematic of Aviation Risk Management Controls and Recovery measures



Aircraft Operator:

Demonstrates their ability to meet the requirements of the BAR Standard to the independent Audit Company.

Audit Companies:


Overseen by the BPO in their ability to meet the requirements of the BARS Program.

BARS Program Office (FSF):

Independent management of the Program,
Independent quality checking of auditing and audit
report production.


Independent External Audit:

Independent evaluation of the BPO to deliver
customer needs of the Program.




Geographic Spread
(Countries: [#Operators/#Audits])



* As at 01 Apr 2017




Close Out Rate Performance

Critical Control Performance - Fuel Rates of non-conformity





Basic Aviation Risk Standard BARS Audit Question Master List

P	Ref	 BARS Audit Question	Operational Categories	BARS Standard Mapping	ICAO/Source Mapping
P2	FLT 1.07.03	The Operator should ensure IFR fuel load calculations include fuel for start-up, taxi, en route, approach and transit to an alternate destination (if required). [BC3.4]	Std	3.4	A6 P1 4.3.6.3 A6 P3 S2 2.3.6.4
P2	FLT 1.07.04	The Operator should ensure IFR fuel load calculations include a variable reserve of 10% of total trip fuel. [BC3.4] A P2V is available for this question. See the latest P2V BARS Notification for further information.	Std	3.4	A6 P1 4.3.6.3 A6 P3 S2 2.3.6.3.1
P2	FLT 1.07.05	The Operator should ensure IFR fuel load calculations include 30 minutes fixed reserve. [BC3.4]	Std	3.4	A6 P1 4.3.6.3 A6 P3 S2 2.3.6.3.1
P2	FLT 1.07.06	The Operator should ensure the minimum fuel carried on any VFR flight plan meets the responsible regulatory authority requirements. [BC3.5]	Std	3.5	A6 P1 4.3.6.3 A6 P3 S2 2.3.6.2
P2	FLT 1.07.07	The Operator should ensure VFR fuel load calculations include a 30 minute fixed reserve and a variable reserve equal to 10% of trip fuel. [BC3.5] A P2V is available for this question. See the latest P2V BARS Notification for further information.	Std	3.5	A6 P1 4.3.6.3 A6 P3 S2 2.3.6.2
	FLT 1.08	AIRCRAFT FUEL CHECKS	Std		
P2	FLT 1.08.01	The Operator should have a procedure to ensure that fuel supplied to an aircraft is tested utilizing water detection capsules or equivalent. The PIC should ensure the quality of the fuel is acceptable for the operation of the aircraft. [BC4.1]	Std	4.1	

AVIATION SAFETY ALERT

AIRCRAFT ELT INSTALLATIONS



1. Background

Date of Incident:	Various	Aircraft Type:	Various
Who this impacts:	All aircraft operators	Operation Type:	All aviation operations

2. Details

A number of Emergency Locator Transmitters (ELTs) have failed to transmit distress signals after an aircraft crash. Several of the accidents reviewed (both aeroplanes and helicopters) were supporting the resource sector. The absence of ELT signals to Search and Rescue (SAR) aircraft and satellite receivers resulted in the delayed discovery of the accident sites and rescue and recovery of personnel.

In most cases the ELT units were either displaced from the mounting (including detachment of the transmitting antenna), burnt out or shielded by wreckage preventing the ELT from performing to design standard. The intent of the ELT design is for the crash forces to automatically activate the transmitter which then transmits an emergency radio signal containing the identification and location of the accident aircraft to SAR organizations. These transmissions are a key component in the location and rescue of personnel once an accident has occurred.

In response to this issue, the US National Transportation Safety Board (NTSB) has previously provided the US Federal Aviation Administration (FAA) with [Safety Recommendation A-10-169](#), requiring a detailed inspection of an aircraft's ELT to ensure it is mounted correctly and in accordance with manufacturer's specifications.

The recurring failure of the ELT as a critical control in mitigating the consequence of an aircraft accident means it is imperative that alternate mitigating controls (such as flight following) are considered and implemented.

3. Major Root Causes

In addition to ELT failure caused by crash forces greater than the design standard experienced in an accident, three other possible failure modes can be considered: (1) Incorrect installation of the ELT, (2) loosening of the ELT retention strap during normal operations; and (3) ELT unserviceable prior to the accident.

4. Recommendations

Contracted aviation service providers should be encouraged to:

- Ensure aircraft ELTs are mounted and retained in accordance with the manufacturer's specification [\[NTSB A-10-169\]](#) during annual inspection; and
- Review alternate controls associated with identifying downed aircraft such as satellite flight following or scheduled radio calls in accordance with [Flight Safety Foundation BARS 12.4, 12.5 and 25.13](#).

Aviation Safety Alert Number 003

BARS Incident Alert 13-01



Tropic Air C208 Caravan - Accident

1. Background

Date of Incident:	25 Nov 2013	Location:	Gulf Province Papua New Guinea
Aircraft Type:	C208 Cessna Caravan	Operator:	Tropic Air
Role:	Passenger Transport		

2. Details

The single-engined Cessna Caravan operated by Tropicair crashed into a river while flying from Kimuri to Purani in Gulf province yesterday afternoon.

The Accident Investigation Commission says 10 people were on board and seven survived.⁽²⁾

3. References


- (1) <http://aviation-safety.net/wikibase/wiki.php?id=162508>, accessed 26 Nov 2013;
- (2) <http://www.abc.net.au/news/2013-11-26/three-killed-in-png-plane-crash/5117600>, accessed 26 Nov 2013;
- (3) <http://www.thenational.com.pg/?q=node/60216>, accessed 27 Nov 2013.

[BPO contact details](#)
+61 1300 557 162 / +61 3 9650 6450
bars@flightsafety.org

Incident Alert 13-01

The information in the BARS Incident Alert has been sourced from publicly available data and is provided as a notification to BMOs relating to BARS Registered Aircraft Operators.





- 150 aircraft operators have been audited since Nov 2010
- 29 different countries represented
- 143 301 audit questions asked to see 10 411 non-conformities raised
- 6 data analysis reports completed on the data from the Program including external loads, geophysical operations, off shore helicopter operations and the repeat finding analysis
- 10 quality reports generated looking at quality control and assurance aspects of the Program
- 100% close out rate on the non-conformities in the last 18 months
- 50 active auditors in the Program
- Across the current 108 operators listed in BARSoft we touch 62 000 employees.
- Of the operators who have been audited in BARSoft there are 1003 fixed wing aircraft and 557 rotary wing aircraft listed for use on a BMO contract
- 17 Technical Advisory Meetings and 13 Audit Company review meetings have been conducted in the system of governance for the Program

RPAS - BOW-TIE



BASIC AVIATION
RISK STANDARD

