## ZK-NBU

(B747-400)

## Inflight Wing Panel Separation NZ99 AKL-NRT

John Shepherd

Safety Investigator – Engineering and Maintenance

Operational Safety – Air New Zealand







## Maintenance Activity

- Inducted for Phase CO1 Check
- Check Included Repeat Alert Service Bulletin
  - (Post pylon modification inspection)
- Interrupted maintenance
  - Removed from hangar
  - Re-inducted/removed several times
- Complete 26 days after original induction
- Inflight Panel separation
  - 1st flight after check

## Maintenance Interruption

- Regular Occurrence
  - "Window of Opportunity for Procedural Error"
  - Existing Work Packages Robust enough to enable program interruption ??
  - Procedural Defences to capture activities "introduced" during interruptions ??

## First Maintenance Interruption

#### Handover Report

"All panels re-installed ready for park outside – marked with red X – only minimal screws holding closed. S/O raised for this work. All removed parts put in shelving and marked NBU"

## Temporary Panel Installation

- Four screws (out of 125)
- Shift Handover Report
- No other references
- Exposure to the environment?
- X Common practice not formalised
- Visibility

	HAND OVER REPORT	DH DETOF
su PERI	1908 / PRODUCTION LEADER / TEAM LEADER	
IME OF	0700 TIME OF 1830 DETE 04.08.0	۶٤.
пем	JOB I STRIUS	(DISK & EMP. No.
0	REF 5/0 50531359 /0010 17EM 2.  870 246 - REQUIRES FURTHER REVOCK  OF CREMSON AREA THEN RECHOCK OF  REMAINSING THEKUESS.  FOR REF SRM 55-10-01 Date: 1 V	?
	\$\( \) 505 31 381 \  \( \) 0010 \ TO \  \( \) \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	?
g 5/	S/G 505-31 758 & 505-31301 - POLS REQUES PANDERS + ROPAT.  Only A Course OF John LEFT In INTERIORS RES LOSANTING WORKENEDS OF PARTS.	?
¥ Z	S/O SOSSILION - DOUBLE PLANT HAS CORROSION PITS - WILL PROVIDE RE- USTALLED ROPENY FOR PARK OUTSIDE - MANUEL WITH REPORK - ONLY MINIMUM SCREWS HOLDING CLOSED S/O RANGED FIRST THIS WORK ALL REMOVED PARTIS PUT 10 SHELVING AND HANCE NEW!	?

Why were the items and Report not signed off or transferred?

Why was the omission not identified during documentation check?

1000	63792 SBtINT)/747-54A2 82/INBOARD PYLON INSPIN					
	FILON INSPECTION - CLOSE ACCESS - ALRESTOS					
3	JOB DESCRIPTION					
	Reference Document - BOE SB 747-54A2182 Rev 00.					
	Complete and certify tasks detailed in applicable reference document accomplishment instructions.					
	Observe reference document Notes, Cautions, Warnings, and general safety precautions.					
	Raise Service Orders for any additional work, or work arising.					
-	A. Pylon Inspections - Close Access:					
	Pylon No #2					
	(1) Wing leading edge gap cover installed.					
i	(2) Diagonal brace func pin access doors installed					
	(3) Midspar fitting fuse pin access doors install (Inboard pylon only). AMM 54-62-00.					
9	(4) Mid-pivot pin access doors installed (Outboam pylon only).					

AMM 54-62-00.

AMM 54-62-00.

AMM 54-62-00.

Strut access doors installed.

(6) Trailing edge fairing doors installed.

# Generic Task Card Produced from Service Bulletin

**Unnecessary Task** 

No Reference Manual for Procedures


Inappropriate Panel Identification

#### Panel Identification Inconsistencies

- SB (All Pylons)
  - "Gap Cover on Wing Leading Edge"
- 747-400 AMM (#2 and #3 pylons)
  - 511CT/611CT
  - "Access Panel Upper Inboard Nacelle"
- 747-400 AMM (#1 and #4 pylons)
  - 521/621FT
  - "Access Panel Upper Outboard Nacelle Gap Cover"
- Task Cards
  - " Wing Leading Edge Gap Cover"

#### Target: SB(INT)/747-54A2182/INBOARD PYLON INSPTN

			PYLON INSPECTION - CLOSE ACCESS - AIRFRAME				
os			JOB DESCRIPTION	WRK	BY	QC	СНК
)1	Cor	mplet	ce Document - BOE SB 747-54A2182 Rev 00.  te and certify tasks detailed in applicable ace document accomplishment instructions.				
	Obs	serve	reference document Notes, Cautions, Warnings, neral safety precautions.				
		ise S ising	Service Orders for any additional work, or work				Market 1
	A.	Pylo	on Inspections - Close Access:				
			Pylon No #2	7		1	5
		(1)	Wing leading edge gap cover installed.	PT	O	Ro	/
6,33.0	BIGHAL	(2)	Diagonal brace fuse pin access doors installed. AMM 54-62-00.	-4	ū47	M	eon
	AGEST 9	(3)	Midspar fitting fuse pin access doors installed (Inboard pylon only). AMM 54-62-00.	N	ites	L	1
		(4)	Mid-pivot pin access doors installed (Outboard pylon only). AMM 54-62-00.	\[ \sqrt{1}	A	5	3
		(5)	Strut access doors installed. AMM 54-62-00.	PE	el tier7	M	100
		(6)	Trailing edge fairing doors installed. XCAP AMM 54-62-00.	len	4310	70	132



## **Duplicate Tasks**

Generic operations for two or more identical tasks for different and unrelated activities.

#### Generic Task Cards

- Signature Block PTO
  - Created Hand-written instruction
  - Existing Hand-written Task Correction History
  - AOP Process Existed for Task Card Correction
    - No response/feedback from Lead Hands/ Supervisors
    - No response from Planners
- Planners
  - No Human Factors training
  - No formal Tech-writer training

## Preparation for Despatch Task

#### The Final Defence

"Carry out external walk around check.

Ensure all access panels are secure"

### "Prepare for Despatch" Task Card

- Brief description
- Area visibility
- No Line / Terminal Services acceptance check
- B767
- B737
- Two hour task assigned to one person
- Task delegation (Normal Practice)
  - At Risk Behaviour or Normal Behaviour?
- Signed by one person
  - At Risk Behaviour or Normal Behaviour?

#### Issues

- Task / Procedure Design
- Maintenance Activity Control / Monitoring
- Supervision
- Safety Culture
- Maintenance Practices

Determining human error is to understand why people did what they did, not judge them for what they did not do.