



## Introduction

- Dennis Hill
  - Owner Aviation Auditors & Aviation Educators
  - Commercial Pilots Licence
  - Instructor rating
  - Diploma Audio Engineering
  - Graduate Certificate Aviation Safety and Risk Management
  - Graduate Diploma Accident Investigation Aviation
  - Principal Auditor
  - Contracted Quality & Safety Manager for CASR Part 145 MRO's



## Aim of today

Case Study: Metroliner Trim Runaway

**SMS Limitations:** Influencing change

SMS Bubble: Limited to the organisation

Improving safety beyond the organisation itself, beyond the SMS Bubble.



#### Context

- The Organisation is no longer in operation
- Was an Aerial Work AOC
- Had its own CASR 145 MRO
- Mixed fleet of Metro aircraft, AC, DC, CC
- Experienced one accident
- Experiencing around 34 SMS reports monthly



## The Incident

- Late 2014
- Routine flight, freight only, single pilot
- Auto pilot engaged ALT HOLD, resulted in trim down runaway
- Trim was operating in reverse sense





## The Investigation

- Investigated in accordance with SMS
- Pitch servo had been replaced in previous maintenance visit
- Pitch servo found to be operating in reverse sense




## Installation instructions

The servo actuator is supplied from the factory with the clutch set at 5in lbs or less, and wired to cause the capstan to rotate in a **counter-clockwise direction**, when system voltage is applied to Pin 3, and Ground to Pin 4 of the **servo connector**. Prior to installation in the aircraft, the servo clutch must be adjusted and the direction of rotation established as called out below.

Note: If the servo direction needs to be reversed from CCW to CW, reverse the corresponding wires on the servo connector.



#### IMPROVING SMS – LESSONS LEARNT METROLINER TRIM RUNAWAY





## Investigation findings

- Servo overhauled in Australia Not the OEM
- Overhauled iaw Engineering Order
- OEM restricted access to technical data
- EO does not require rotation direction test
- Release of component in a condition that does not meet the technical data requirements
- Servo can be used on large range of installation, Citations, Metro, Chieftans etc



# Investigation findings

- Restriction of access to data by OEM
- No post installation test of autopilot (65 step process)
- Installation manual was not up to date
- Current data requires aircraft wiring to be changed to change rotation



## **OEM** data

- ICA allowed wiring change for 20 years
- When OEM changed tech data to aircraft side wiring, no communication to say so
- Revision status in document: Revised Pitch Servo Installation per drawing # 76771



## Problems

- Repeatable incident
- Servos still being released without rotation direction verification
- Could have been SIL, or SB by OEM
- Could have been an alert from CASA SDR unit



## OEM and SMS Investigation

- Component sent to OEM for repair
- Request was made to supply photos for investigation
- OEM did not participate in SMS Investigation



#### Recommendations

- Do not purchase units that had been overhauled in accordance with an EO, only if done in accordance with the CMM
- Request OEM to issue a Service Information Letter highlighting the change from servo wiring to aircraft side wiring. No response received.
- Request CASA to issue an alert to industry, AWB, AD etc. No response received.



## **SMS Limitations**

- The OEM would not participate other than to provide a simple strip report, which added minimal value to the investigation.
- CASA SDR unit did not participate other than to ask what we had done, they did not seem to appreciate the wider impacts or potential for recurrence.
- The local overhaul shop did not want to share information, or allow us to view the EO, which may have helped identify additional problems.

## SMS Bubble

- Very little reach beyond the organisation itself
- No power to influence change to third parties
- Limited ability to share with industry
- Restriction of access to data
  - No ability to demand data



# Improving SMS

- Third party cooperation
- Reporting stream to CASA and ATSB where proper assessment is carried out





