

SOCIAL MEDIA &



IT'S EFFECT ON AVIATION SAFETY











Grade 1 Flight Instructor

- Tail Wheel
- MPPC
- Retractable
- Aerobatics
- Formation
- Spinning
- UPRT Specialist



Tow Pilot
Air Experience Instructor (Not Current)

RAAus Flight Instructor (Previously CFI)

- Tailwheel
- Manual Propeller
- Low Performance
- High Performance
- 2 Stroke
- Formation



HOO - CASR Part 138

Banner Towing







RAAus and CASR Part 141 FLIGHT TRAINING



DESIGN FEATURE & FLIGHT ACTIVITY TRAINING

SPECIALISING IN LOSS of CONTROL InFlight PREVENTION TRAINING









MAINTENANCE

16 Years - RAAF Avionics Technician

GSE

F111

Caribou

RAAF Museum

Maintenance Planning Specialist

6 Years – CANADA

Airlines & GA QA & Avionics Maintenance Manager

LAME – Australia, Canada, PNG

DASH 8 – Classic & 400 GA Fleet Management

2 Years - Royal Air Force of Oman

Maintenance Planning Specialist PC9, C130, BAC111, SC7, Jaguar Paper Records – Full Electronic Records

8 Years - PNG National Jet/Cobham

(OKTEDI) FIFO SBE for three DASH 8-100

Flight Safety Solutions

Aircraft Owner/Operator Support Sport & Recreational Aviation Maintenance Training Fully Compliant Electronic Aircraft Records System (CASR43 Ready)





LSA & EXPERIMENTAL AIRCRAFT MAINTENANCE TRAINING CASR Part 43



AIRCRAFT OWNER 101 TRAINING

CONTINUING
AIRWORTHINESS
MAINTENANCE
ORGANISATION









THIS PRESENTATION IS NOT 2ND OR 3RD HAND IS 100% PERSONAL EXPERIENCE

IMPROVEMENT OF THE SYSTEM FOR SAFER AVIATION IS THE DESIRED OUTCOME















WHAT IS AIRWORTHY?

According to ICAO Annex 8, the term airworthy means


"The status of an aircraft, engine, propeller or part when it conforms to its approved design and is in a condition for safe operation."







FIRE TRIANGLE










COMPONENTS FOR MAINTENANCE INTEGRITY







MAINTENANCE SAFETY CIRCLE





Manufacturer builds aircraft/component to a "STANDARD" & monitors airworthiness, issuing "ICAW"

Owner/Operator selects and monitors the appropriate maintenance program "WHAT"

Regulators and Administrators review reports, liaise with the Manufacturer to issue "ICAW"

Maintainer performs maintenance IAW the appropriate standards of airworthiness "HOW"

ALL aviators keep accurate and visible records and adhere to a "JUST" reporting culture

Pilot ensures <u>ALL</u> maintenance "HAS" been performed before flight





Manufacturer builds aircraft/component to a "STANDARD"

TYPE CERTIFIED	SPORT AIRCRAFT	EXPERIMENT AL	LIMITED
FAR23 FAR25 Approved by a Regulator	ASTM International formerly known as American Society for Testing and Materials "SELF CERTIFYING"	KITS Must be built exactly per the plans to produce a clone copy of the manufacturers production built SLSA to be eligible for ELSA certification. NAPKIN	WARBIRDS Ex-Military
		Modification to KITS or CAO 95-10	







Owner/Operator selects and monitors the appropriate maintenance program "WHAT"

AIRCRAFT OWNER 101 TRAINING FLIGHT TRAINING PROVIDERS







Maintainer performs maintenance IAW the appropriate standards of airworthiness "HOW"

- Standards Removal of CAR 30
 - CASR Part 43
 - RAAus L2 Training

Standards
Hard to make a buck – "Grey

Maintenance"
Inadequate documentation
IMPORTATION

MEV PROPELLER IMPORT - FIRST OF TYPE







Pilot ensures <u>ALL</u> maintenance "HAS" been performed before flight

1.2 Maintenance includes all of those actions which are carried out on a recreational aircraft to ensure the aircraft is fit for flight and includes inspection, adjustment, repair and the incorporation of modifications. Maintenance **excludes** the design or redesign of modifications. The pilot- in-command of a recreational aircraft must ensure that the aircraft is fit for flight, currently registered and correctly maintained before each flight.

RAAus Technical Manual 4.1

"I just want to go flying" - Blind Trust

Changing Standards – Maintenance Releases







ALL aviators keep accurate and visible records and adhere to a "JUST" reporting culture

"Do I have to report that?"


What's the point??





Regulators and Administrators review reports, liaise with the

to monitor airworthiness, Manufacturer to issue "ICAW"



Manufacturers REQUIRED issuing "ICAW"


2.4 Continued operational safety monitoring of light sport aircraft

CASA requires the manufacturer to use a system to monitor and correct safety-of-flight issues in accordance with an approved LSA standard. For as long as an LSA is registered in Australia, it remains the manufacturer's responsibility to monitor for unsafe conditions in aircraft and notify owners/registered operators of corrective actions. It is incumbent on the manufacturer to evaluate all significant defects and correct any unsafe condition that may exist in the remaining fleet. To achieve this, the manufacturer should provide a method for the aircraft owner/registered operator to report any in-service difficulty.













MAINTENANCE SAFETY CIRCLE





Manufacturer builds aircraft/component to a "STANDARD" & monitors airworthiness, issuing "ICAW"

Process for "IMPORT"

Owner/Operator selects and monitors the appropriate maintenance program "WHAT"

The absence of "OVERSIGHT"

Understanding "RESPONSIBILITY"

Regulators and Administrators review reports, liaise with the Manufacturer to issue "ICAW"

#HARDTODOTHERIGHTTHING

Maintainer performs maintenance IAW the appropriate standards of airworthiness "HOW"

The importance of reporting "CULTURE"

Avoiding

"GREY MAINTENANCE"

ALL aviators keep accurate and visible records and adhere to a "JUST" reporting culture

Understanding the "RISK"


Pilot ensures <u>ALL</u> maintenance "HAS" been performed before flight







CONTRIBUTORS TO LOSS OF MAINTENANCE SYSTEM INTEGRITY










Are Social Media Platforms a Reliable Source for Information?









ACCESSIBILITY

- Manufacturers Data Hard to find
- Social Media Easy

CONTENT

Anything is fair game

SOURCE DATA

Whatever the individual feels like posting

VALIDATION

There is no authentication of data

CREDIBILITY

• The more "Followers", the more the credibility.







WHY ARE PEOPLE TURNING TO SOCIAL MEDIA FOR HELP TO FIND AIRWORTHINESS DATA?







WHAT DID WE DO BEFORE THE




WHERE DID WE FIND MAINTEANCE DATA??






Flight Safety Solutions

TRANSPORT CATEGORY AIRCRAFT














GENERAL AVIATION AIRCRAFT









ANZSIS – JUNE 2023

WELCOME TO THE 21ST CENTURY




Aviation Hub	
& the ATP® Store	
Username	
Password	
Log In	
Forgot password?	
Don't have an ATP Username & Password?	
Register Here	
The ATP Aviation Hub [™] streamlines aircraft maintenance workflows and improves processes with anywhere, anytin access. Learn more about the ATP Aviation Hub [™] •	
Get the ATP Aviation Hub Mobile App Download on the App Store Get it from Google Play Get it from Microsof	t





Flight Safety Solutions

WELCOME TO THE 21ST CENTURY



CERTIFIED AIRCRAFT

- Expensive to subscribe
- Packages

OLDER AIRCRAFT

- Scanned .pdf of original manuals (no search)
- Manufacturers not likely to update
- ICAW by Service Bulletins

NEWER AIRCRAFT

Interactive and searchable manuals







AIRCRAFT MAINTENANCE MANUALS & ILLUSTRATED PARTS CATALOGS

BRAKES








CERTIFIED AIRCRAFT -

BELLANCA .



BOTTOM VIEW

BRAKE RESERVOIR ----

PEDAL ASSEMBLY

MASTER CYLINDER -

VIEW FUSELAG

REMOVAL OF BRAKE HYD

- a. Brake system is Disconnect hydra parking brake va
- b. The master cylin
- brake pedal and


BELLANCA

bolt heads, w c. On aircraft e (Gerdes), rem control wire.

floorboard su

REPLACEMENT OF "O See Figure 6-4)

a. Remove snap r Note direction respect to va move inlet and Replace "0" r outlet fitting into body so surfaces. Ins assembly. (Se



BELLANCA



PARKI





DECATHLON SERVICE MANUAL

REPLACEMENT OF "O". RINGS IN MASTER CYLINDER (GERDES) (See Figure 6-5)

a. If aircraft has Gerdes master cylinder (see identification label on cylinder body). Remove snap ring on forward end of body. Remove piston rod assembly. Clean and replace any defective parts. Replace all "O" rings and teflon piston seal. Reassemble.

INSTALLATION OF MASTER CYLINDER

a. Install master cylinder in reverse order of removal.

INSTALLATION OF PARKING BRAKE VALVE (GERDES)

- a. Install valve in reverse order of removal.
- b. Connect park brake control wire temporarily. Check travel on control to maintain 2 inch travel on control.
- c. Connect all hydraulic lines.

6-13. ASSEMBLY AND INSTALLATION OF MAIN WHEEL (See Figure 6-2)

- a. Pack bearing with grease.
- b. Install tire and tube on proper wheel halves. Install three thru bolts and nuts.
- c. Install bearings, felts and retainer rings.
- d. Reinstall wheel on axle. (Axle brake torque plate and wheel pant mounting bracket must be attached to gear leg previous to installing wheel assembly.)
- e. Install axle nut to allow wheel to turn free yet not fit loose on axle. Cotter key nut. Install dust cover or wheel pant.



Reissued 5-1-79

6-11

CERTIFIED AIRCRAFT






FIGURE AND INDEX NUMBER	PART NUMBER	DESCRIPTION	UNITS PER ASS'Y
23- 1 2 3 4 5 6 6 7 8 9 10 11 12 13 14 15 16	4-1624 A-315 AN526-1032-6 AN936-A10 69F 1/8 x 1/8 4-1624-1 62056 4-1624-2 4-1624-2 4-1624-2 1-10399 1-10180 2-2162 AN822-4D A-850-1 AN526-1032-22 AN960-10 AN365-1032 2-2111-6 AN937-4D AN960-716 AN924-4D 1-10181 AN742-4 AN3-3A 1-2577-1 AN365-1032 1-2584 AN365-1032 4-1621 A110-10 62029 AN816-4D MS20392-2C17 AN380-2-2	LINE - RESERVIOR VENT TEE LINE (RIGHT SIDE) LINE (LEFT SIDE) CONTROL - PARKING BRAKE PLACARD - PARKING BRAKE HOSE ELBOW PARKING BRAKE VALVE	1 2 2 1 1 1 1 1 2 2 2 2 1 1 1 1 1 1 L/1R 2 2 2 4 4
22	2-2111-8 AN833-4D AN960-716 AN924-4D	LINE ASSEMBLY (REQ'D FOR WRAPAROUND INSTALL- ATION) ELBOW (REQ'D FOR WRAPAROUND INSTALLATION) WASHER NUT	2 2 2 2
68		Reissued 5-	1-79







LIGHT SPORT AIRCRAFT -

P92

5

TECNAM

Line Maintenance

Seats are made out of metal tubing framework with fabric covered for adjusted by sliding backward and forward along rails fixed to cabin t below seat cushions.

Cabin floor is constructed of light alloy and features matting.

Entire fuselage, wing and other exposed surfaces are finished with a Wash using only water, mild detergent and chamois. All parts in Per with lukewarm soapy water. In any case, never use, on this kind of s of solvent

4.8 Landing Gear

The main landing gear (see fig. 4-12) consists of two special steel sp elastic cushioning of landing loads.

The two steel spring-leaf struts are attached to the fuselage underside Two rawhide liners (2 3) are inserted between each spring-leaf and t spring-leaf to the edge of the girder via a light alloy clamp (4) while leaf-spring to the girder.




Figure 4-12 Main land

Doc. Nº 92-13-120-

Wheels are cantilevered on gear struts and feature hydraulically actu located on cabin tunnel between seats. Main gear wheels mount Air-

Hydraulic circuit shut-off valve (2) is positioned between seats. With activates parking brake function.

TECNAM

Line Maintenance Manual




Figure 4-13 Hydraulic Brake Circuit

To remove the leaf-spring struts proceed as follows:

Remove cabin seats by sliding them forward

Hoist aircraft onto supports

Disconnect brake fluid line unscrewing the upper link of the external line tract near fuselage bott on lines to prevent spillage

Loosen bolts (part.5 fig. 4-12) of the aluminum clamp (part 4 fig. 4-12) that secure spring-leaf to Remove bolt connection between inboard end of spring-leaf (part.6 fig. 4-12) and main girder Remove gear strut by pulling outward from fuselage

Reinstall using reverse procedure. It is however necessary to eliminate any trapped air: once the in reservoir is at normal level, bleed air through dedicated valve. For best results, use external pu valves allowing trapped air to escape through open reservoir.

If braking action appears degraded, check and eventually replace main gear brake pads Refer to Periodic Inspection Chart in Section B for any service operation to main gear

Doc. Nº 92-13-120-00

TECNAM

P92 Echo Classic Dolesto Line Maintenance Manual

4.8.1 Main Gear

Removal of main gear wheel (see fig. 4-16a and 17) Removal of a single wheel is carried out as follows:

- · Hoist aircraft onto supports
- Release parking brake
- . Remove fairing (1) by releasing bolt (2) and the three Phillips screws (3) that hold fairing to plate
- Remove bolt (4) and cup (5)
- Remove wheel lock nut (6)
- Unscrew 4 brake disc assembly bolts (See Figure 4-14 and Figure 4-15 (8))
 Carefully remove wheel assembly with both hands




Figure 4-14 Figure 4-15 Removal of main sear wheel

Main Gear

4.8.2 Removal of cup-bearing from main gear wheel



Revision Date: 11-27-2008 Revision Number: 1.00


Doc. Nº 92-13-120-00





LIGHT SPORT AIRCRAFT

- IPC



COSTRUZIONI AERONAUTICHE TECNAM S.r.I.		P92-ECHO	GRUPPO 4	1		
<u> </u>	I ECNAM se	PARTS CATALOG	CARRELL	0		
CARRELLO POSTERIORE – FRENO "MARC-INGEGNO"						
FIG.	P/N	DESCRIZIONE		Q.tà		
	92-8-002-000	COMPLESSIVO CARRELLO PRINCIPALE		2		
1	92-8-300-1	BALESTRA		2		
2	92-8-202-1	ASSALE		2		
3	92-12-301-3	BICCHIERE FERMA RUOTA		2		
4	92-12-301-2	ATTACCO CARENATURA (OPT.)		2		
5	UNI 5737	VITE A T.E. CR8.8 M8 L=150 MM		2		
6	UNI 6592	RONDELLA PIANA D=8		2		
7	UNI 7473	LOBO M8 MB		2		
8	92-12-301-4	STAFFETTA FISSAGGIO CARENATURA		2		
9	92-8-410-1	CARENATURA RUOTA SX (OPT.)		1		
	92-8-410-2	CARENATURA RUOTA DX (OPT.)		1		
10	92-12-301-1	PASTICCA FERMA CARENATURA (OPT.)		2		
11	UNI 1751	RONDELLA ELASTICA D=6		2		
12	UNI 5739	VITE A T.E. M6 CR8.8 L=16 MM		2		
13	UNI 5737	VITE A T.E. M4 CR8.8 L=35 MM 2		2		
14	UNI 6592	RONDELLA PIANA D=4 2		2		
15	UNI 7473	DADO AUTOBLOCCANTE M4 2		2		
16		PNEUMATICO 5.00-5		2		
17		CAMERA D'ARIA		2		
18	157-00800	PIATTO COPRI-RUOTA		2		
19	102-00600	VITE A T.T. M3.16 L=6 MM		6		
20	92-8-204-1	CRAVATTA ANCORAGGIO BALESTRA		2		
21	92-8-206-1	SPESSORE IN COMPOSITO	i	4		
22	92-8-205-1	SPESSORE		2		
23	UNI 5737	VITE A BRUCOLA M8 CR8.8 L=60 MM		6		
24	UNI 6592	RONDELLA PIANA D=8		12		
25	UNI 7473	DADO AUTOBLOCCANTE M8		6		
26	UNI 5737	VITE A T.E. M6.35 CR8.8 L=39 MM		8		
27	UNI 6592	RONDELLA PIANA D=6		8		
28	UNI 7473	DADO AUTOBLOCCANTE M6.35		8		
29		PINZA FRENO		2		
30		PASTICCA INT.		2		
31		PASTICCA EST.		2		
32		SUPPORTO PINZA		4		
33		DISCO FRENO		2		
		1	1			
_		Dicembre	1998 Pag. 4-8			





LIGHT SPORT AIRCRAFT - AMM

BRAKE CALIPER









LIGHT SPORT AIRCRAFT -

AEROPRAK I-22LS Airplane Maintenance Ma

5 Brake system

The main wheels are equipped with Matco n includes: expansion tank, master cylinder with supporting plates, brake disks, copper tube brake system is filled with transmission fluid A mfg. The amount of the fluid in the system c tank that must be not less than half of the tank

When servicing the brake system it may be r disconnection air gets into its cavities whi necessary to fill the brake system with fluid to

To fill the brake system with braking fluid

- check the level of the braking fluid in th WARNING! Use only the fluid that is the fluids of different grade. This may of the brake system.
- remove the cover set the parking brake - remove protecting cap from the brake tube with the inner diameter of 3 mm (The other end of the tube put into a
- completely submerged into the fluid; while holding the tube loosen the nipple
- pump the braking fluid through the syst appearing completely in the transparer time of such pumping); while doing it expansion tank to avoid air inflow into t
- after air bubbles disappear, tighten th and put on the protecting cap;
- repeat above actions for the other whe

To fill the brake system with braking fluid in t following:

- remove the stick cover:
- remove the stick from the roll torque tul
- remove the parking brake;
- remove the clamps holding the brake s put the stick on the longitudinal beams up and pump the brake system through
- re-assemble everything in the reversed

WARNING! When filling the brake system it in the amount of 1 to 2 volumes of the expans

For more detailed information about maintena visit its manufacturer web site: http://www.mal

> Recommended special tools: none. Necessary parts/materials: 300 mm of

AEROPRAK I-22LS Airpiane Maintenance Ma

INSPECTIO

Part No.	Description	
-	Expansion tank	
See Matco P/N	Master cylinder	
See Matco P/N	Parking brake valve	
See Matco P/N	Brake unit assembly, right	
See Matco P/N	Brake unit assembly, left	
See Matco P/N	Brake disk, right	
See Matco P/N	Brake disk, left	
-	Copper tubes	
-	Reinforced rubber hose	

Instructions:

5.1 Remove the top engine cowling. Inspect cracks in its housing and cap. If the tan brake system must be filled with braking the beginning of this section.

> Check the fluid level in the tank and refil half of the tank. Make sure the tank attac plastic cable ties if necessary.

Recommended special tools: none. Necessary parts/materials: none.

5.2 Remove handles from the control levers the horizontal panel. Inspect the master are detected, it must be removed for repa

In order to remove the master cylinders, (

- remove the left seat;
- remove the panel between pilot seats:
- disconnect the control cables of the e
- engine and trim tab ends, and then from undo the screws of the control lever unit
- block the reinforced rubber hose near
- clamp and disconnect it from the master - disconnect the copper tube connecting t

WARNING! When disconnecting the bra fluid may spill out.

- remove the control lever unit assembled
- detach the master cylinder from the con

To install the master cylinder perform the re-assembling fill the brake system follow this section. Then adjust the control syst described in the corresponding sections of

If no defects were detected in the mas reversed order.

AEROPRAK I-22LS Airplane Maintenance

Recommended special tools: none Necessary parts/materials: none.

5.3 Remove the handles from the contri and the horizontal panel. Inspect the

> If any leak is detected the valve mus In order to remove the parking brake

- block the reinforced rubber hose cylinder by squeezing the hose with cut the plastic cable ties fixing the v
- undo the screws attaching the valve disconnect the copper tubes from the
- To install the parking brake valve t order. After assembling fill the bra

instructions described in the beginning If no defects are detected in the par reversed order

Recommended special tools: none Necessary parts/materials: none.

Remove the wheel fairing. Inspect to any leak is detected the brake unit m

To remove the brake unit, do the follo

- put the wheel chokes under the nos
- lift the airplane using a jack place fuselage bottom skin for the MLG s
- unlock and undo the brake disk scr
- remove the wheel and brake disk:
- disconnect the copper tube from the - disconnect the brake unit from the screws of the brake unit) and remove

To re-install the brake unit perform assembling fill the brake system follo of this section.

Check the brake pads for integrity a 2.54 mm (0.1 in). The wear may be the braking pad. In case of seriou replaced. In order to do that, detach the brake pads (the braking syster brake unit). For more detailed instrupads contact the manufacturer (Mato

If the wear is within the permissible order. Before re-installing the attach on their thread.

Recommended special tools: none Necessary parts/materials: Loctite

AEROPRAK I-22LS Airpiane Maintenance Manual

A22LS-AMM-02

5.5 Define the nature and degree of the brake disk wear. For that remove the brake disk as described in 0. Measure the brake disk thickness at its working surface. It must be at least 3.3 mm (0.13 in). If the disk thickness is less than that, the brake disk must be replaced. For more detailed instructions on servicing and replacement of the brake disk contact the manufacturer (Matco mfg).

If the wear is within the permissible limits, re-assemble everything in the reversed order. Before re-installing the attachment screws of the brake disk apply Loctite 222 on their thread.

Recommended special tools: none.

Necessary parts/materials: Loctite 222.

5.6 Remove the handles from the control levers of the throttle, elevator trim tab and brakes, horizontal panel, main wheel fairings and pilot seats. Inspect the tubing of the brake system for leaks and damage. Pay special attention to the joints. If leaks and damage is detected replace the corresponding portion of the tubing. To obtain additional technical support contact the manufacturer.

After re-assembly fill the brake system following the instructions described in the beginning of this section.

After inspection (repair) re-assemble everything in the reversed order. Before reinstalling the pilot seats apply Loctite 222 on the thread of the attaching bolts.

Recommended special tools: none.

Necessary parts/materials: Loctite 222.








LIGHT SPORT AIRCRAFT

AEROPRAKT-22LS Illustrated Parts Catalog

A22LS-IPC-02





NAME: Set of 6x6 wheels with brakes PART NO.: A22LS-02-4000 WEIGHT: 13.5 kg

НАИМЕН.: Комплект колес 6x6 с тормозами HOMEP: A22LS-02-4000 BEC: 13.5 кг



NAME: Master brake cylinder PART NO.: A22LS-02-5000 WEIGHT: 0.2 kg

НАИМЕН.: Главный тормозной цилиндр НОМЕР: A22LS-02-5000 ВЕС: 0.2 кг



NAME: Braking system fittings (a set) PART NO.: A22LS-02-5001 WEIGHT: 0.13 kg

НАИМЕН.: Фитинги тормозной системы (комплект) НОМЕР: A22LS-02-5001 ВЕС: 0.13 кг



AEROPRAKT-22LS Illustrated Parts Catalog

A22LS-IPC-02







LIGHT SPORT AIRCRAFT -

AEROPRO EUROFOX MAINTENANCE MANUAL

INSTRUMENTS

	Туре	Serial No.
Airspeed indicator		
Altimeter		
Vertical speed indicator		
Bank indicator		
Magnetic compass		
Radio		
Atitude indicatore		
Transpomder		
Fuel pressure		
Engine instruments - Turn-indicator		
Engine instruments - Oil pressure		
Engine instruments -Oil temperature	i	i .
Temperat. head cylinder		
Engine-hour meter		

III. STORAGE BATTERY

Туре	DRYFIT A512/16G5	
Voltage	12 V	
Capacity	16 Ah	

The storage battery is located behind the right-hand pilot's seat.

2.5 Landing Gear

Landing device is a type of trigear undercarriage with a controllable nose wheel

The main landing gear is formed of lever-type swinging legs of laminat, Wheels with low-pressure tires of 14x4 size are provided with hydraulic disc brakes operated from the left-hand pilot's seat. As custom-tailored, the brakes may be interconnected mechanically to be operated from the righthand seat as well.

The nose-wheel landing gear is welded of steel tubes. The nose wheel is equipped with a tire of 12x4 size.







LIGHT SPORT AIRCRAFT

37B	BMP Brake & Fitting Lubricant	RIOP	4.00
388	Set of O-rings gaskets for brake cylinder / Evektor	.0	5.50
	Set of O-ring for old version of master brake cylinders	OO0000000	11.00
398	Set gaskets for brake cylinder / Evektor	9	12000
40B	Springs under the balls for brake cylinder / Evektor	COLUMN	3.30
418	Set of rubber O-rings and pistons for old brake system for master cylinders on pedals.	0000000	135.30
428	"Bleed screws" for our brake callipers M3 – old version of callipers	-	1.10
43B	metal balls – valve for bleed screws M4	2 11111	3.30

13	496.40
5 00	
MARKET STATE OF THE PARKET	457.30
	457.30
	12.10
	35.00
Toyles	
13	141.90
11 11	
	1.10
	0.70
	6.60
	54.60

7	39.40
	7.70
	1.10
	4.90
	522.40
	760.70
	202.90
	392.20
	104.80

		54.60
	Forte	2.10
7		19.70
7	FO.	41.50
		41.50
		1.10
	- 2	12.10
		<i>0</i>

1	348.70
	424.80
	424.80
	83.00
	4,40
	6.60
	91.70

	596.20
	685.00
	500.80
7	78.60
	901.20
	348.70
1	348.70
	348.70







THE IMPORTANCE OF USING AIRCRAFT ILLUSTRATED PARTS CATALOG

AIRCRASH INVESTIGATORS BAC111 – WINDSHEILD BOLTS







NOTICE OF CORRECTIVE ACTION

N°06-LSA

Issue Date: 17-05-2012

Page 1 of 1

NOTIFICATION 🗵	SERVICE BULLETIN	SAFETY ALERT	
A/C and s/n AFFECTED	All models		
TIME OF COMPLIANCE	Nil		
WORKING PLACE	Nil		

Subject: Use of not original spare parts for Tecnam airplanes.


Scope: Tecnam became aware that some aircraft owners/operators sometimes do not use original spare parts; in particular, Tecnam would like to notify that recently an operator replaced fuel hoses, in accordance with time limits reported on the AMM, but he used NOT original fuel hoses, that, after investigation, have been shown being incompatible with approved fuels.

In this case, safety of flight has been affected and this event originated the present communication that has the scope of making sensitive all owners/operators about this subject.

Tecnam takes care of customer's safety and strongly recommends using only original spare parts, tested and selected over 20 years of experience and, at the same time, informs the customers that it shall not be liable for aircraft damages due to the use of not original spare parts.















	COSTRUZIONI AERONAUTICHE	P92-ECHO	GRUPPO 7	
11	TECNAM s.r.l.	PARTS CATALOG		IMPIANTI
	CRUSCOTTO			
FIG.	P/N	DESCRIZIONE		Q.:
1	92-12-106-1	CRUSCOTTO		1
2	92-9-907-1	PALPEBRA		1
3	92-12-113-1	SUPPORTO BUSSOLA		1
4		INDICATORE VELOCITA'		1
5		ALTIMETRO		1
6		INDICATORE TRIM		1
7		BUSSOLA MAGNETICA		1
8		CONTAGIRI MOTORE		1
9		TEMP. TESTA CILINDRI		1
10		INDICATORE POSIZIONE FLAP		1
11		LUCE GENERATORE		1
12		TEMPERATURA OLIO		1
13		PRESSIONE OLIO		1
14		CONTAORE		1
15		LIVELLO CARBURANTE DX		1
16		LIVELLO CARBURANTE SX		1
17		INTERRUTTORE LUCI NAVIGAZIONE		1
18		INTERRUTTORE LUCE STROBE		1
19		INTERRUTTORE FARO ATTERRAGGIO		1
20		INTERRUTTORE FLAPS		1
21		INTERRUTTORE MAGNETI		1
22		VIROSBANDOMETRO		1
23		STARTER CON CHIAVE		
24	92-12-111-1	TAPPO PICCOLO		2
25	92-12-111-2	TAPPO GRANDE		2
26	92-12-123-1	COPERCHIO VANO RADIO		1
Ì				
		Diamil	bre 1998	Pag. 7-14


















































TECNAM RIVETS













WHICH RIVETS SHOULD BE USED?

Is there a Structural Repair Manual?

How does the maintainer know what rivet to use in what location?


Didn't you see Air Crash Investigators BAC111 windshield??





WHERE DO I FIND MAINTEANCE

 $D\Delta T\Delta 22$



Know where to find the information and how to use it - That's the secret of success.

— Albert Einstein —

AZ QUOTES







Citing Facebook as a reference – Harvard Style

https://www.youtube.com/watch?v=uYUvsuJsR0k








DISCLAIMER





Sebruary 19 · 😉

Hello fellow aviators. I have a starter motor problem and would like to replace it. I live in Italy and spare parts are not available quickly here. Does anyone know if the starter motor is the same as in a car? do you know if a different version of moped was mounted compared to mine? thank you all. I attach photos.








ANZSIS - JUNE 2023

















EXPERIMENTAL AIRCRAFT ENGINES







Flight Safety Solutions

EXPERIMENTAL AIRCRAFT ENGINES

ICAW



- No published Maintenance Schedule
- No IPC
- No Service Bulletin structure

- RIVONMUNICATION

- Long reply period for emails
- Difficult to get on the phone

PARTS SUPPORT

- Shopping list
- List not updated when parts proven to be inadequate







Hi AM Owners

I also have experienced a partial alternator failure on my engine. Just noticed over the last few flights the alternator dropping offline for random lengths of time, sometimes 1 min to 20 mins. I have also experienced from new a huge load (60 amps) everytime I bring on the alternator online after start. This high load gradually unloaded over 30 to 60 seconds, but it caused the engine to drop over 200rpm and it would not of been good for my batteries or other electrical components. My new Alternator hardly effects my engine rpm now. I replaced it with this new OEX brand alternator from Repco Australia https://www.repco.com.au/.../oex-alternator.../p/A9614552

The original alternator had no branding, no serial numbers. I now have 37 hours on the engine.

I suggest all owners to consider this upgrade as we require electrical power to remain in the air !!!

I have filed a safety notice with https://flightsafetysolutions.com.au/manufacture-support/
I encourage everybody who has had the same problem to do the same no matter where you are in the world.



REPCO.COM.AU

OEX Alternator 12V 40A Denso Style - DXA4035

It starts with the parts - At Repco we have a wide range of Alternators. OEX Alternator 12V 40...







Denso alternator is what we use. The number is 16678-64014. Please check alternator belt tighteness every 10 hours. It has to be tight to make alternator work. Also check alternator connection and wire when alternator is not providing electric.

Starter replacement will work from Metro, Swift.







Today Dad and I changed out our run in oils from the engine and gearbox. While unwinding the oil sump plug by hand it broke away from the thread. I admit that I did not use a torque wrench when I last installed this plug but it was not stupidly tight. In my opinion the plug is too lightly manufactured, there is very little structure to the plug outside of the magnet. I don't want to use a sump plug that has the ability to break easily even if it is slightly over torqued. This is what I now have in my aircraft https://www.supercheapauto.com.au/.../pre.../SPO1851048.html










Laying my lack of knowledge bare here, chaps. Couldn't find these bits of plumbing in the manual. Please advise:









On the subject of hoses, the ID o pipe is about 25mm, with the bar quite tight to seal it. Is this norma different to everyone else?



0 2



nthat's no good 😡 the barbs are really only for a clamp to sit behind to stop a hose pulling off. Did you have to do that to the hose on the aluminium pipes as well, or just the expansion bottle? What I might do is 'double clamp' so that there is a clamp in the correct position and a clamp on the barb $\ensuremath{\mathfrak{U}}$

Like Reply 7w

Ill answer my own question- the expansion bottle pipe turns out to be the same size as the ali pipes in the kt, so it must be ok \odot

Like Reply 8w





Smek


2 comments

(~) Send

estion for the ones using the uavionix tail beacon. Are vo

Question for the ones using the uavionix tail beacon. Are you guys just trimming the inside of the light hole until the tail beacon fits?

If so, are you using a dremel?














ANZSIS – JUNE 2023










Erika's Post

×





This is the front bulkhead inside the spinner of my -- one of the nut plates? Rivnuts? broke off.

- 1) Does anyone know the part number for this and the rivets?
- 2) Any thoughts why this would happen?
- 3) Any thoughts about whether it is easier to replace the bulkhead or just the nut? We have a second one cracking as well.

Have reached out to A&P and but checking here in parallel while I wait for them to get back to






















Please

Here is the fix.

contin lock or

Please

Here is



The screw in the photo is secured with both locktite and safety wire.

I used a MS24677-14 which is a socket head cap screw with a drilled head in place of the original screw. I had to use three washers because of the length of the screw. A MS35265-41 1/4 in filister head screw would be a better choice, but I couldn't find one locally.


I discussed the situation with TruTrak this morning, and Lucas said that they would be investigating the problem.

Pat


































20	21-8-210-1	LEAF SPRING CLAMP PLATE	2
21	92-8-206-3	LEATHER SHIM	2
22	92-8-205-1	SPACER SHIM (ALI)	2
23	UNI5737-D8L60	HEX SOCKET HEAD BOLT M8 CR8.8 L=60 MM	6
24	UNI6592-D8	FLAT WASHER D=8	12
25	UNI7473-D8	SELF LOCKING NUT M8	6
26	UNI5737-D6L39	BOLT T.E. M6.35 CR8.8 L=39 MM	8
27	UNI6592-D6	FLAT WASHER D=6	8
28	UNI7473-D6	SELF LOCKING NUT M6.35	8
29		BOLT T.E.	4
30		WASHER	4
31		NUT	4




















































RAAus

Reported via OMS

TECNAM

Communicated with local distributor

CASA TALK TO RAAus







IT'S HARD TO DO THE RIGHT THING

#ITSHARDTODOTHERIGHTTHING

SOCIAL MEDIA IS HERE TO STAY — EMBRACE IT

HUMANS WILL ALWAYS LOOK FOR THE EASIEST ROUTE





IT'S HARD TO DO THE RIGHT THING









DECISION TIME







DECISION TIME








DECISION TIME

Safety Circle Breakdown – WHO IS MAINTAINING THE SIGNPOSTS?









RED ALERT

CONFIRMATION BIAS

TRUST BUT VERIFY







THE BUBBLE FILTER

This applies to Google search results too!




Don't be this person /



CHAINSAWSUIT.COM

i've heard the rhetoric from both sides... time to do my own research on the real truth





















CONTRIBUTORS TO LOSS OF MAINTENANCE SYSTEM INTEGRITY










SWISS CHEESE ROULETTE









DON'T BRING PROBLEMS – BRING SOLUTIONS

OVERSIGHT

of all parts of the Maintenance Safety Circle

Simply do the job everyone is supposed to do.





MAINTENANCE SAFETY CIRCLE



Manufacturer builds aircraft/component to a "STANDARD" & monitors airworthiness, issuing "ICAW"

Owner/Operator selects and monitors the appropriate maintenance program "WHAT"

Regulators and Administrators review reports, liaise with the Manufacturer to issue "ICAW"

Maintainer performs maintenance IAW the appropriate standards of airworthiness "HOW"

ALL aviators keep accurate and visible records and adhere to a "JUST" reporting culture

Pilot ensures <u>ALL</u> maintenance "HAS" been performed before flight







DON'T BRING PROBLEMS – BRING SOLUTIONS

OVERSIGHT

of all parts of the Maintenance Safety Circle

Simply do the job everyone is supposed to do.

CAMO

For GA and RA

Cost, Culture and Desire.





QUESTIONS














		I	
20	21-8-210-1	LEAF SPRING CLAMP PLATE	2
21		LEATHER SHIM	2
22		SPACER SHIM (ALI)	2
23	UNI5737-D8L60	HEX SOCKET HEAD BOLT M8 CR8.8 L=60 MM	6
24	UNI6592-D8	FLAT WASHER D=8	12
25	UNI7473-D8	SELF LOCKING NUT M8	6
26	UNI5737-D6L39	BOLT T.E. M6.35 CR8.8 L=39 MM	8
27	UNI6592-D6	FLAT WASHER D=6	8
28	UNI7473-D6	SELF LOCKING NUT M6.35	8
29		BOLT T.E.	4
30		WASHER	4
31		NUT	4
	•		







LSA SERVICING BULLETIN

N° P92/001

N° P2004/001

page 1 of 1

Information	Recommendation		Mandatory	\geq
DATE ISSUED	August 7, 2007			
DATE EFFECTIVE	August 7, 2007			
SCOPE	TECNAM LSA airplanes m	nodels:	P92 Echo Super – P2004 B	Bravo
SUBJECT	Landing Gear attachment	bolts		

DISCUSSION:

A US flight training school LSA aircraft P92 Echo Super had an incident where the landing gear leg folded back under braking as the aircraft was rolling out after landing. The possible cause is the uncorrect torque value of the interested bott or a defective bolt.

During the inspection of the aluminium alloy clamp an ovality was found in the attachment bolt hole: although this ovality is normal in order to permit some accomodation during the assembly.

APPLICABILITY:

TECNAM LSA airplanes models:

- P92 Echo Super
- P2004 Bravo

CORRECTIVE ACTION:

At the next service interval or within the next ten hours of flying, a LSA mechanic, A&P mechanic, FAA Reapir Station, or an authorized factory representative must inspect the landing gear attachment bolts. The visual inspection includes:

- Attachment bolts (inspect the conditions and the torque value 24.6Nm 217lb in)
- Aluminium alloy clamp inspection for deformation or cracks;

If the bolts must be replaced, please request to your TECNAM dealer the following P/N:

P/N	Description	Q.ty
MS20005-24	Attachment bolts	4
MS21042-5	Self-locking nut	4
MS20002C5	Countershank washer	4
MS20002-5	Plain washer	(as required, 4 min.)

DO Design Office	OoA Office of Airworthiness	HDO Head of Design Organization
Prepared	Document release Approval of the whole modification Compliance C.L.	Declaration of Compliance
Mr. Fabio Russo	Mr. Michele Oliva	Mr. Luigi Pascale Langer

If the bolts must be replaced, please request to your TECNAM dealer the following P/N:

P/N	Description	Q.ty
MS20005-24	Attachment bolts	4
MS21042-5	Self-locking nut	4
MS20002C5	Countershank washer	4
MS20002-5	Plain washer	(as required, 4 min.)







LSA SERVICING BULLETIN

N° P92/001

N° P2004/001

page 1 of 1

Information		Recommendat	tion		Mandatory	≥ K
DATE ISSUED		August 7, 2007				
DATE EFFECTIVE		August 7, 2007				
SCOPE		TECNAM LSA ai	rplanes n	nodels:	P92 Echo Super – P2	2004 Bravo
SUBJECT		Landing Gear att	achment	bolts		

ILLUSTRATED PARTS CATALOG





Doc. 92/65 Ed:1 Revision:3 February 2009







SERVICE BULLETIN

N°18-LSA

Date: 12th September 2011 Rev. 2 of 13th September 2011

page 4 of 11

3. MLG nuts substitution Replace the laterals and central nuts according to following figure 2 and applying the torque values indicated in table 1: AN365-624A MS20002-5

Figure	2. MLG	leg attac	hment

Description	Part number	QTY	Torque value			
Central bolts	MS20006-64	2				
Lateral bolts	MS20005-24	4	//			
Stop nut for lateral bolts	AN365-524A	4	15 +/- 1 Nm			
Stop nut for central bolts	AN365-624A	2	25 +/- 2 Nm			
Washer under Lateral bolts	MS20002C-5	4				
Washer under Central bolts	MS20002C-6	2	//			
Washer under Lateral Stop Nuts	MS20002-5	4	//			
Washer under Central Stop Nut	MS20002-6	2	//			

Table 1

NOTE

To avoid a main landing leg detachment from the fuselage Tecnam recommend that the nuts must be replaced one at a time and the correct torque value must be applied at end of all nuts installation.

Part number	QTY	Torque value				
MS20006-64	2					
MS20005-24	4					
AN365-524A	4	15 +/- 1 Nm				
AN365-624A	2	25 +/- 2 Nm				
MS20002C-5	4					
MS20002C-6	2					
MS20002-5	4	//				
MS20002-6	2					
	MS20006-64 MS20005-24 AN365-524A AN365-624A MS20002C-5 MS20002C-6 MS20002-5	MS20006-64 2 MS20005-24 4 AN365-524A 4 AN365-624A 2 MS20002C-5 4 MS20002C-6 2 MS20002-5 4				

Table 1

NOTE

To avoid a main landing leg detachment from the fuselage Tecnam recommend that the nuts must be replaced one at a time and the correct torque value must be applied at end of all nuts installation.





	COSTRUZIONI	AERONAUTICHE
-	TEC	NAM

P92 Echo Super de luxe SERVICE MANUAL

Section B

INSPECTIONS
AND SERVICING

	Type of inspection		CTION . (HOURS)
		100	Special
	MAIN GEAR		•
1	Check brake system (tank, pump, pipes and calipers)	•	
2	Replace brake pads		600(a)
3	Check at sight leaf spring force struts, connection tie and clamping pivot	•	
4	Remove gear struts and check camber and condition		1200
5	Inspect principal wheel for good state and clamping	•	
6	Remove wheels, clean and lubricate bearings		600(b)
7	Integrity fairing and relative attachments (if installed)	•	

- (a) When brake pad thickness is below 2.4 mm
- (b) initially at 100 hours







SERVICE BULLETIN

N°17-LSA

Date: 11th August 2011

page 1 of 3


Information		Recommendation	X	Mandatory		
A/C AFFECTED	P	P2002 (series with fixed gear) all serial numbers P92 (series): all serial numbers P2004 Bravo: all serial numbers				
TIME OF COMPLIANCE		Within 10 flight hours if total flight hours less than 100, then every 100hrs				
WORKING PLACE	c	n place.				

Subject: Main landing bolts torque values check

Scope: In order to ensure a better connection between the main landing gear leaf-springs and the fuselage, it is recommended to perform a torque values check of the MS bolts in time of compliance provided in this bulletin.












 Locate the interested areas and proceed to install the Support Plate P/N 21-2-1114-1 as shown in the drawings.





TECNAM
7 MONTHS WAIT


RAAus OWNER - MANUFACTURER

CASA
TALK TO RAAus





































RAAus

Reported via OMS

TECNAM

Communicated with local distributor

CASA TALK TO RAAus









- 5 DEFECT REPORT AND AIRWORTHINESS NOTICE ADMINISTRATIVE PROCEDURES
- 5.1 Once the defect report is submitted through the Occurrence Management System the originator will be sent a confirmation of receipt advice.
- 5.2 Defect reports will be given a reference number for the originators record and all reports will be reviewed by the RAAus HAM.
- 5.3 Every defect report will be reviewed by the RAAus HAM and one or more of the following actions may be taken:
 - (a) A summary of the defect and its outcome are made available on the RAAus website via the following link https://www.raa.asn.au/safety/accident-and-defect-summaries/
 - (b) An Airworthiness Notice will be prepared. Samples are available on the RAAus website www.raa.asn.au under Safety – Technical – Airworthiness. Due to the wide nature of possible subjects, individual Airworthiness Notice format may vary but will generally follow the format of Topic – Background Discussion – Action Required. Airworthiness Notices may be published in "Sport Pilot" magazine. Depending on the significance of the defect, copies of Airworthiness Notices may also be forwarded by the HAM to all RAAus registered owners of the aircraft type by mail or via email.
 - (c) For other than LSA aircraft, the rectification action specified in the Airworthiness Notice is to be undertaken or arranged to be undertaken by aircraft owners within the period specified in the Notice.
 - (d) For LSA Aircraft, as no modifications can be made without Manufacturer's approval, RAAus will issue the Airworthiness Notice as an advisory to members, and RAAus will also alert the aircraft manufacturer about the defect found, and request they investigate.
 - (e) Aircraft/Component manufacturers may be advised of the defect or deficiency and requested to undertake rectification action and advise all known owners of the affected aircraft or component.





Occurrence Management

Occurrence Number	Occurrence Type	Occurrence Date	Status	Outcome
OCC2923	Defect	29th August 2022	Outcome Approved	STATUS: Under review OCCURRENCE DETAILS SUBMITTED TO RAAUS: Ordered parts from the manufacturer and found parts or critical systems with varying tolerances.
OCC2919	Defect	20th August 2022	Under Investigation	STATUS: Under review OCCURRENCE DETAILS SUBMITTED TO RAAUS: During pre-flight, the windscreen skylight was found to have multiple rivets pulled out of the screen.
OCC2838	Defect	13th June 2022	Under Investigation	STATUS: Under review OCCURRENCE DETAILS SUBMITTED TO RAAUS: Defect: 42 Vortex Generators fell off the aircraft. The remainder were able to be removed with light finger pressure.
OCC2777	Defect	29th March 2022	Assigned For Delegation	
OCC2751	Defect	24th March 2022	Assigned For Investigation	STATUS: Under review EXTRACT FROM REPORT SUBMISSION: The aircraft was found to have a crack in the plastic skylight.
OCC2680	Defect	12th January 2022	Im Review	STATUS: Under review EXTRACT FROM REPORT SUBMISSION: During pre-flight it was noted that where the elevator cable exits the empennage near the horizontal stabilizer, the aircraft skin has rubbed the protective coating from the cable exposing the strands. Nil strands damaged at this stage
OCC2776	Defect	11th January 2022	Under Investigation	STATUS: Under review EXTRACT FROM REPORT SUBMISSION: The lower longerons for the aircraft frame showed signs of corrosion
OCC2668	Defect	18th December 2021	Sm Review	STATUS: Under review EXTRACT FROM REPORT SUBMISSION: During taxi, the aircraft as unable to turn left with full left rudder applied. Found was RH pedal on LH seat binding on the control arm to the stop. They found the rudder significantly off to the RH side when the pedals centralized. Deflections to the right in excess of the movement noted in the AMM allowing the elevator and rudder to come in contact with each other. This movement MAY, in the right conditions, prevent elevator authority due to binding of the elevator on the rudder trim tab assy. Also found the rudder cable tensions too low with only 0.020" lockwire used on turnbuckles (one of which is not of aviation grade). Adjusted rudder control stops to meet AMM requirements of 155 degrees both left and right. Cable tensions set to AMM requirements. Independent inspection carried out and the aircraft was returned to service.





Airworthiness Notices

Publication Title	Summary	Publication Date
AWB 02-066 Issue 1 Maintenance - Aircraft Immersed in Water <u>Download Document</u> (PDF <u>104 kb</u>)		18 Mar 2022
Safety Notice - Bristell LSA <u>Download Document</u> (PDF <u>III</u> 116 kb)		19 Feb 2020
EASA Pipistrel AD 2019-0128 Download Document (PDF 499 kb)	EASA AD 2019-0128 - Pipistrel Virus SW 121 aeroplanes - Seat belt attachment bolts.	6 Jun 2019
Costruzioni Aeronautiche Tecnam P2008 Series Aeroplanes 2018-0072 Download Document (PDF 210 kb)	After an occurrence report of an engine fire, it was identified that, in some locations on the engine firewall, steel patches that had been attached with use of sealant material had, likely as a result of the fire, detached in the engine compartment. The related technical investigation concluded that more aeroplanes might be affected. This condition, if not detected and corrected, could lead to propagation of an engine fire to other critical areas, possibly resulting in loss of the aeroplane.	28 Mar 2018
TL Ultralight SB 3.S.SI.2017 Download Document (PDF @ 3 mb)	Damage to the flap drive torque tube in the fuselage.	18 Jan 2017


Advisory Notices

Publication Title	Summary	Publication Date
Skyreach Bushcat Seat Belt Harness Inspection • RAAus ADN - Bushcat1.pdf [270 kb]		5 Nov 2021
Safety Notice - Bristell LSA - 20 Feb 2020 (00000002), pdf [116 kb]		19 Feb 2020
Pipistrel Aircraft SB-162-00-80-006_A00 • <u>SB-162-00-80-006_A00 Fuel pump switch retrofit.pdf</u> [<u>#</u> 260 kb]	SB-162-00-80-006_A00 Fuel pump switch retrofit— This is a recommended SB and applies to all ALPHA Trainer LSA aircraft up to and including s/n 958 AT 912 LSA, that do not already have a dedicated fuel pump switch installed in the switch panel.	19 Nov 2019
Pipistrel Aircraft SB-162-00-80-005_A00 ■ SB-162-00-80-005_A00 Introduction of POH revision B00.pdf [■ 845 kb]	SB-162-00-80-005_A00 Introduction of POH revision B00— This SB mandates POH replacement and applies to certain AT LSA aircraft (see affected aircraft). Please note that it is a MANDATORY service bulletin.	11 Nov 2019
Zlin Aviation - Mandatory service bulletin • Zlin Safety Alert n.092.pdf [■] 2 mb]	All Savage Planes and models Visual check for possible sleeves corrosion on all stainless steel wires used for ailerons, rudder, stabilizers (*) flaps controls (*). (*) not for Shock Cub and Shock Ultra	20 Aug 2019
Fly Synthesis Texan 550 - Inspection of Nose Gear Steering Plate • RAAus ADN - Texan 550 Nose Gear Steering Plate1.pdf [■ 660 kb]	An inspection is to be performed before next flight on all aircraft to ensure the steering plate has no free-play on the mounting bolt and nut.	10 May 2019
Aeroprakt SA A22LS-16-(inspection of rudder cables) • <u>SA A22LS-16-(inspection of rudder cables).pdf</u> [■ 165 kb]		2 Apr 2018





TECNAM STRUCTURAL CORROSION







CYLINDER HEAD COOLANT HOSES

SCHEDULED MAINTENANCE ACTION IAW ROTAX 912ULS LMM

5 Year rubber component replacement. Includes all required Rotax rubber parts

NOTE: Airframe maintenance schedule does not specify a life limit for the airframe rubber components





IDENTIFIED DEFECT

Airframe replacement rubber parts received from manufacturer were not "Fit for purpose"





INVESTIGATION

Rubber coolant hoses provided from manufacturer were too large a diameter for the male component

Rubber coolant hoses installation require different size openings at each end.

Rubber coolant hoses provided from manufacturer were identified as Automotive hoses only obtainable from South Africa

Different aviation grade hoses were tested to determine "Form, Fit & Function"





REPORTING ACTION

RAAus OMS Submission

RESPONSE: NIL

Email to Australian Distributor and the aircraft manufacturer suggesting an AMOC and a recommendation for a Service Bulletin to advise all other owners, maintainers and pilots.

RESPONSE: NIL





RESOLUTION

1 Owner pestered Aircraft Manufacturer

RESPONSE: LOA for his aircraft only

05/03/2023

LETTER OF APPROVAL CH213C

This letter serves as an approval for to use replacement parts as listed in Cooling System.

Note: Although these hoses and fittings comply with aviation specs the specific hoses and fittings have not been used/tested by the specific hoses and fittings have not can't be held liable for any incidents etc. which may arise from it including replacements.





BUSHCAT COOLANT HOSES

RESOLUTION

EVERY OTHER BUSHCAT OWNER

Will be blissfully unaware of the problem **UNTIL** they have to deal with the issue themselves.






TECNAM CORROSION



































CONTRIBUTORS TO LOSS OF MAINTENANCE SYSTEM INTEGRITY







MAINTAINER TRAINING STANDARDS

TYPE

B1/B2 CASR Part 66 Syllabus Theory CASR Part 147 - 90Weeks \$55K or Self Study +

Exams - CASA Practical - Logbook

CASR PART 43

AMTC

SPORT AIRCRAFT

Approved Maintainers under

xams -NOQDesiron on-line exam Practical -Nil Required (Recommen ed)

CASARARARIT243 No SMITTE

Recognition in not experience Theory

Exams - NIL

Practical – Observed competency by 2 other L2 holders or LAME

Theory – Structured Course (4 Days)
Exams – Set by Administrator
Practical – Structured Workbook Cou

EXPERIMENT

Owner builder is the "Manufacturer"

Aircraft ASR PART 43

Aircraft ARecommended oversitht by SAAA during build phase only

Short "Paperwork" course (2 Days) Open book Exam

RAAus – 19 registered – L4 Check


INVOLVEMENT WITH ModificationAlloTKHIS or AO 95-10 (RAMATCI minimum) LIMITED

WARBIRDS

CASR PART 43 AMTC







TOPGUN EFFECT

FIGJAM.



- Manufacturers don't know who owns their aircraft
- Some Manufacturers websites do not help at all
- Administrators are resource poor

TRAINING

- Don't want to make it too hard or expensive.
- Where to find data AC43-13?? Facebook!
- Systems knowledge Why do I need to know that?
- ICAW I changed my oil? Isn't that enough?

TIME

I don't have time for that, I just want to fly.

EXPECTATION

- Its supposed to be cheap
- Its like a car right?

PERCEPTION


- Its just for a hobby.
- It's only an RAAus aircraft

DESIRE

Be a pilot, fly a plane, zoom around the clouds




















Assigning finite resources to achieve a desired outcome in today's world is challenging.

Humans have developed "Risk Assessments" strategies with almost everything we do.





Decision makers use the results of these "Risk Assessments" to assign resources to where they believe it can reduce the risk to "ALARP".

It is common to hear that "loss of life" in a small aircraft is not as big of a risk than in a commercial aircraft.






UNLESS **YOU** ARE THE STATISTIC




























Appropriate training for emergencies is the insurance policy we hope we never need to claim upon.








OUR INDUSTRY NEEDS A HAND

















WHY SHOULD RA/GA UNDERTAKE UPRT

- HAVE TO
- WANT TO
- FINANCIAL ADVANTAGE
- EGO





OWNERS

OPERATORS

PILOTS (Renters)

- Get to live
- Keep aircraft in 1 piece
- Improve proficiency
- Insurance discounts

- Staff get to live
- Keep aircraft in 1 piece
- Keep business operating
- Insurance discounts

- Get to live
- Improve proficiency

Cost savings













 Discovered ICAO Doc 10011 and commenced dissecting the document to develop and deliver appropriate training,

2014 - Present - Delivering and continually developing UPRT (LOC-IPT) elements,

July 2019 — 3 Day workshop with RAAus to investigate LOC-I and where components of UPRT can be embedded into initial training,

2019 – 2022 – Identified significant variations to expected flight standards of competency by flight instructors (RAAus, GA, Specialist & UPRT Providers),

Aug 2022 — Hosted the <u>worlds first</u> UPRT Providers Conference. *Lightly sponsored by CASA, Agile and AON Insurance,*

Oct 2022 — Along with other UPRT Providers and RAAus, invited to speak at the CASA UPRT Workshop in Sydney,

 Working with CASA to develop a UPRT training structure for all levels of pilot (Abinitio through to Instructors),

- Delivered online Stall Workshops (Nov 2022 Free of charge)
- Addressing inquiries to deliver seminars and workshops Australia Wide.



Presently





LOOKING AHEAD

- Interactive On-Line training courses presented by an experienced UPRT Instructor,
- Training videos demonstrating UPRT (LOC-IPT) elements,
- Continue working with CASA/RAAus and Industry to ensure (as best we can) that the data delivered is correct and appropriate,
- Continue working with CASA/RAAus and Industry to develop an effective LOC-IPT and UPRT training structure,
- Roadshows to visit locations Australia Wide to educate both Instructors and Pilots,
- Creation of the "Association for UPRT Instructors". Establishing standards and liaising with the regulator.
- Worlds First UPRT Flight Instructors Workshop (20 January 2023) CASA Endorsed.







https://www.aviationsafetymagazine.com/features/loc-recoveries/?fbclid=IwAR2000a7XCLGrQDj5T6Te1d6S2AHWD6mY2WkMP7wSjXVJjodOo4wYbcTEsU

Teaching plain vanilla unusual attitude recovery for more than 80 years hasn't been successful in keeping the loss of control accident rate under control.

Moving to LOC avoidance and recovery training that emphasizes the why of LOC, the risk factors leading to it, avoiding it and realistic in-flight simulations and recovery is the logical next step.

Besides, the training is a lot of fun.





LOSS OF CONTROL AWARENESS CAMPAIGN

GOAL

- •LOCi Awareness Primacy
- •Improving Pilot Competency

PROCESS

- Develop a UPRT Syllabus of training delivering agreed competencies for the GA/RA Sector.
- •Insertion of suitable UPRT elements into the current VFR Syllabus

BENEFIT

- •Reducing Loss of Life and Hull
- •Reduction of Insurance Costs





WANTED

PARTNERS TO HELP DEVELOP CHANGE











